

PRESSURE DISPLAY

The pressure display is a universal digital display that can be directly connected to the digital barometer to provide a direct display of the pressure and altimeter setting independent of other data processing equipment at the site.

The software of the pressure display is implemented as several independent products, called operation modes. The system configuration can contain several set-ups at the same time, so that one pressure display can serve as a spare part for different types of systems.

A commercial dot matrix printer can be connected to the display's Centronics interface to provide a graphical, printed presentation of data.

