

Service Bulletin

100075 Wind Speed Sensor

Climatronics Corporation
140 Wilbur Place
Bohemia, NY
Ph. 631-567-7300 Fax 631-567-7585
E-mail: service@Climatronics.com

Parts & Service Description

REPAIR AND FIELD MAINTENANCE

A complete repair and service department is maintained at our factory in Bohemia New York. Our factory trained technicians provide professional service using only OEM specified parts and certified alignment equipment.

For those who wish to perform their own maintenance, a comprehensive list of maintenance parts follows the repair menu. Our manuals provide complete maintenance instructions.

RETURN AUTHORIZATION

Prior to any product return, please contact the factory at (631)-567-7300 or e-mail service@Climatronics.com for a return authorization number (RA).

BASIC SERVICE(S)

<i>Ordering No.</i>	<i>Description</i>	<i>List Price</i>
100075SVC-1	100075 WS Sensor Preventive Maintenance & Bench Test Includes bearings & wear items as required.	\$ 105.00
100075SVC-2	100075 WS Sensor, Includes SVC-1, Plus replace electronic circuit board & Bench Test	\$ 225.00
600023	Wind tunnel test 5-10-15 MPH Traceable to NIST includes Threshold. As Found Or As Left. Double for both calibrations.	\$ 215.00
600023-1	Wind tunnel test 6 points, 5 to 30 MPH. Includes threshold. As Found Or As Left. Double for both calibrations.	\$ 390.00
Additional parts as listed below.		

REPLACEABLE/SPARE PARTS LIST

	<i>Part No./ Ordering No.</i>	<i>Description</i>	<i>List Price</i>
	500096	Bearings (two required)	11.00
	Q2-12	Retainer ring	.50
	101441	Wind Speed Cap	30.00
	.126 X .039	Small Cap o-ring	3.00
	SS3-2	Large .010 cap spacer	.50
	102499	Circuit Board (New improved design. Replaces 101080)	100.00
	SS1	Spacer Kit	15.00
	102104	Lexan cup set	140.00
	SC8-5	Cap set Screw (Two Required)	2.00
	SC8-17	Cup Set Screw (Two Required)	2.00
	SC4-10	Base Set Screw (Two Required)	2.00
	102104	Cupset—Black Lexan	130.00
	101287	Cupset—Heavy Duty Aluminum	160.00